

1. Attach the USB cable from the Advanced Breakout board to the USB port on your computer.  
Look for the USB symbol which identifies the USB connection.
2. Route the USB cable away from high voltage cables (such as the power cable and theta power cables).
3. For in ground dynos, be sure to route the USB cable through the pit conduit that does not contain any high voltage cables.  
Refer to your dyno installation guide for additional cable routing information.

